

Xplus

cod. 60.000.102

Sensore sole e vento  
Wind & sun sensor



Portata contatto / <i>Contact capacity</i>	500mA
Temperatura lavoro / <i>Operating temperature</i>	-20°C / +55°C